Pattern Detail and Specifications



| đ | Color: | Miner |
|---|----------------------------|--------|
| | Fiber Content: | 100% |
| (| Fabric Repeat: | 14.25' |
| | Fabric Width: | 54" |
| | Fabric Backing: | Backe |
| 4 | Fabric Grade: | А |
| | Fabric Direction : | RR |
| | Country of Origin : | China |
| | | |

Mineral 100% Polyester 14.25" X 14.49" 54" Backed A RR Chine

FLAMMABILITY:

| CALIFORNIA TECH TB117-2013 : UFAC: | PASS CLASS 1 | | | |
|--|---|---------------|--|--|
| PERFORMANCE: | | | | |
| Abrasion: Light Fastness: | Average Min. 15000 Cycles Min. 40 Hours - Min. Class 3 | | | |
| Color Fastness to Crocking | | | | |
| | Wet: | Min Class 4.0 | | |
| | Dry: | Min Class 3.0 | | |
| CARE & CLEANING | | | | |
| Cleaning Code: | | W | | |

"Spot clean only with water based shampoo or foam upholstery cleaner. Pretest a small, inconspicuous area before proceeding. Do not overwet. Do not use solvents to spot clean. Pile fabrics may require brushing with a non-metallic, stiff bristle brush to restore appearance. Hot water extraction or steam cleaning is not a recommended cleaning method. Cushion covers should not be removed and laundered. To prevent overall soiling, frequent vacuuming or light brushing with a non metallic, stiff bristle brush to remove dust and grime is recommended. When cleaning a spill, blot immediately to remove spilled material. Clean spots or stains from the outside to the middle of the affected area to prevent circling. Use a professional furniture cleaning service when an overall soiled condition has been reached."



1823 Eastchester Drive. High Point, NC 27265. USA www.Culp.com